


Aras model




The Flame cut is the best method for cutting strap metal.

This machine is used to industrial structure product and is a good replacement of Guillotine.

Advantage

- Cutting Simultaneously and avoid of Distortion of the cut pieces.
- Installing 6- 16 cutting head
- Clutch System
- Timing belt gearbox
- reduced cutting width to at least 3 cm by adaptor
- Electric control of height of torches





BORNAABZAR.com

ماشین آلات شیار برش - راسته بر

Voltage	AC220 v 50hz
Motor	Stepper motor
Feedback	None
Max Speed machine	1000 mm/min
Max Axes error	1 mm
Max Thickness	70 mm

Technical INFO

Details	INFO
Max Cutting area	2*6
Number of cutting head	6
MIN distance of cutting head	11 cm
Motor	Step motor
Min motion speed	100 mm/min
Max motion speed	1000 mm/min



BORNAABZAR.com

دنیای مدرن ابزار مدرن
برنا ابزار X.B.A.T.I
بزرگ ترین تولید کننده ماشین آلات CNC

ماشین آلات ابزار پرش - ساخته بر

