

Multi Spindle



Wood milling machine are used to carving on the wood. This machine used for mass production

The device is able to carve one pattern up a larg number of workpieces. (Depending on the number of spindles).

In fact, the device is able to produce several of work pieces.

Voltage	Ac 380 v 50 Hz
Normal spindle power	2.2 kw
Work	360*250*30 cm
Max spindle	22000 rpm
Power Consumption	3 kw
Motor	Ac servo motor
Gearbox	Planetary gearbox
Axis	X-Y-Z
Motion system	Rack & Pinion
Max control system error	0.01 (mm)
Max machine error	0.1 (mm)



specification
Machining on all types of wood and wood products
Curve and groove cutting and drilling
Three axis
Set the starting point to work from any location of Desk
Reading g code from standard design software
The T shape table for Keep the work piece

Software
Preview
Edit plan & G cod
The initial Settings

Option
Vacuum table to holding the work piece
Suction system to collect chip wood
Spindle 5.5 kw
Increase number of spindles
Add rotary System
Install remote control system

Water Spray M



دنیای مدرن، ابزار مدرن...


برنا ابزار



بزرگ ترین تولید کننده ماشین آلات CNC

BORNAABZAR.com

ماشین آلات منبت چوب



Multi Spindle M



دنیای مدرن، ابزار مدرن...

برنا ابزار X.B.A.T.I

بزرگ ترین تولید کننده ماشین آلات CNC

BORNAABZAR.com

ماشین آلات منبت چوب

