





## H BEAM MANUFACTURE MACHINE



At first put the web and flange like T shap in the machine then move in the machine, the operator start the spot welding on the Structures. The next rotate the structure and add the other Flange and H shape formed. the motion system of machine supply by motor, gearbox and Hydraulic jack.



### Advantages


- Equipped with two 350 MIG welding machine (order)
- Up and down jack for fix the structure
- down Pedal to make operate easier.
- Tables before and after the machine with moving pulley.



- Powerful Hydraulic system

Voltage	AC380 v 50hz
Web height	200 - 1500
Web plate thickness	6 - 32
Web Width	200 - 600
Flange plate thickness	6 - 40
Length conveyor	24m
Motor	5.2 KW
Transition system power in pulley	Gears and chains
Transition system in web and flange fixture	Ball Screw
Transition motor in web and flange fixture	Hydro Motor





دنیای مدرن، ابزار مدرن... **پرنا ابزار** B.A.T.I

بزرگ ترین تولید کننده ماشین آلات CNC

BORNAABZAR.com

ماشین آلات III ساز

